

Release Note for VigorAP 810

Firmware Version: 1.1.6
Release Date: November 9, 2015
Applied Models: VigorAP 810

With this high cost-efficiency VigorAP 810, computers and wireless devices which are compatible with 802.11n can connect to existing wired Ethernet network via this VigorAP 810, at the speed of 300Mbps. Easy install procedures allows users to setup a network environment in very short time - within minutes, even inexperienced users. Just follow the instructions given in this user manual, you can complete the setup procedure and release the power of this access point all by yourself!

New Features

- Support Wireless Station Control.
- Support Station Statistics in Diagnostics.
- Support Syslog / Mail Alert Setup.
- Support APM Log for Central AP Management.
- Add RTS Threshold/Fragment Length/Rate Adaptation Algorithm in Wireless LAN Advanced Setting page.

Improvement

- Improved: More information about Vigor AP can be displayed on Central AP Management Dashboard.
- Improved: More detailed information of TX/RX will be displayed on Diagnostics>>Wireless LAN Statistics page.
- Improved: Support configuration restored from AP800.
- Improved: Support factory reset for Central AP management.
- Corrected: Speed Test web page did not work on Safari.
- Corrected: Antenna 1T1R mode did not disable left antenna.
- Corrected: Fixed that no Internet access via Wi-Fi with packet of VLAN Tag Priority.
- Corrected: Fixed that no Internet access via Wi-Fi when enabling Management VLAN & SSID VLAN at the same time.
- Corrected: Channel was always "1" when auto channel was used.
- Corrected: A PC, connected to LAN port, could not get IP address from DHCP Server by Station-Infrastructure Mode.

- Corrected: Fixed that TR-069 CPE Username and Password were grayed-out.
- Corrected: USB Temp Sensor stopped working.
- Corrected: Daylight Saving Time of "Mountain Time Zone" was incorrect.

Known Issue

- None

Notes

Modifications

- None